




Structurally Deficient Bridges on the National Highway System Utah - Congressional District 03



Consult your state DOT for the most up-to-date status of bridges.



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 69 structurally deficient NHS bridges in Utah, 4 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	1D 699	I-15 (SR-15) NBL	4.6 MI.NO.NO.BEAVER INTER
2	0C 237	US-6 (SR-6)	3.3 MILES WEST OF DELTA
3	2C 371	SR-201 EBL	NEAR KCC ARTHUR MILL
4	4C 371	SR-201 WBL	NEAR KCC ARTHUR MILL
5	3F 129	I-15 (SR-15) SBL	WEST SIDE OF PAYSON
6	1F 129	I-15 (SR-15) NBL	WEST SIDE OF PAYSON
7	3F 130	I-15 (SR-15) SBL	IN PAYSON
8	1F 130	I-15 (SR-15) NBL	IN PAYSON
9	1C 357	I-15 (SR-15) NBL	1.1 MI NO OF PROVO INTER
10	1C 358	I-15 (SR-15) NBL	1 MI.NO.OF PROVO INTERCHG
11	3C 362	RP I15SB - SR114EB	PROVO INTERCHANGE
12	2C 364	SB.RP.to SR-114EB	PROVO INTERCHANGE
13	1C 360	SR114WB.R.TO I15NB	PROVO INTERCHANGE
14	2C 361	SB.RP.TO SR-114EB	PROVO INTERCHANGE
15	3F 103	I-15 (SR-15) SBL	1.7 MI.SW.SPANISH FK.INT.
16	1F 103	I-15 (SR-15) NBL	1.7 MI.SW.SPANISH FK.INT.
17	3F 104	I-15 (SR-15) SBL	1.5 MI.SW.SPANISH FK.INT.
18	1F 104	I-15 (SR-15) NBL	1.5 MI SW SPANISH FK INT
19	0F 84	SR-189	600 SO.UNIV.AVE.IN PROVO
20	0C 287	US-6 (SR-6)	14.8 MI.EAST OF THISTLE