




Structurally Deficient Bridges on the National Highway System Colorado - Congressional District 02



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 136 structurally deficient NHS bridges in Colorado, 14 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	F-08-F	I 70 SERVICE RD	N. OF DOTSERO INT.
2	F-11-AC	I 70 ML EBND	12.3 MI E OF JCT SH 131
3	F-11-AB	I 70 ML WBND	2.2 MI E OF JCT US 24
4	F-11-AP	I 70 ML WBND	11.4 MI W OF EAGLE-SUMMIT
5	F-12-AS	I 70 ML EBND	3.8 MI WEST OF EAGLE-SUMM
6	F-12-AT	I 70 ML WBND	4.7 MI W VAIL PASS SUMMIT
7	F-12-AL	I 70 ML WBND	4 MI W OF JCT SH 91
8	F-12-AO	I 70 ML EBND	3.5 MI E OF SUMMIT EAGLE
9	F-12-AP	I 70 ML EBND	@ COPPER MOUNTAIN
10	F-15-BL	I 70 ML WBND	8.7 MI W OF JCT SH 74
11	E-16-HW	RAMP TO US 36 SBND	IN BOULDER
12	E-16-HV	SH 121 ML NBND	IN BROOMFIELD
13	E-16-FK	SH 121 ML SBND	IN BROOMFIELD