




Structurally Deficient Bridges on the National Highway System Colorado - Congressional District 03



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 136 structurally deficient NHS bridges in Colorado, 14 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	J-09-D	US 50 SERVICE RD	W. SIDE OF GUNNISON
2	H-09-E	SH 82 ML	ASPEN
3	K-11-G	US 50 ML	14 MI EAST OF DOYLEVILLE
4	P-12-H	US 285 ML	4.8 MI NORTH OF NEW MEXIC
5	O-14-H	US 160 ML	@ BLANCA, 21 MI E OF ALAM
6	N-17-N	I 25 ML NBND	4.2 MI N OF SH10-WLSNBRG.
7	N-17-BG	I 25 ML NBND	1.7 MI NO OF SH10-WLSNBRG
8	N-17-AD	I 25 ML SBND	1.15 MI N WALSENBURG BUS
9	M-17-R	I 25 ML	2 MI NO OF JCT SH 165
10	K-18-AC	US 50 ML	0.6 MI E OF JCT SH 45
11	K-18-CL	I 25 ML SBND	0.7 MI S OF JCT SH 96
12	P-18-M	I 25 ML NBND	IN TRINIDAD
13	P-18-BF	I 25 ML NBND	IN TRINIDAD
14	K-19-U	US 50 ML EBND	0.4 MI W OF JCT SH 96 E
15	L-21-W	US 50 ML	1.6 MI EAST OF FOWLER
16	L-21-G	US 50 ML EBND	4.2 MI EAST OF FOWLER