




Structurally Deficient Bridges on the National Highway System Massachusetts - Congressional District 02



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 187 structurally deficient NHS bridges in Massachusetts, 11 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	A050020U0MHDNBI	ST147 SPRINGFLD ST	RTE 147 AT WESTFIELD RIV
2	N19059100MHDNBI	I 91 SB	1.55 M N EASTHAMPTON T.L.
3	N19059101MHDNBI	I 91 NB	1.55 M N EASTHAMPTON T.L.
4	C1300812HMHDNBI	ST116 SPRNGFLD ST	0.5M S JCT I-90
5	S180150VUMHDNBI	US202 PURPLE HEART	.4 M N CONN RIVER
6	S180160VTMHDNBI	US202 GRANBY RD	.9 M N CONN RIVER
7	S1800712LMHDNBI	ST 47 HADLEY ST	1 M N JCT ST 116
8	S2401614JMHD634	HWY ARMORY ST	AT JCT ALBANY ST.
9	C13011122MHDNBI	ST141 MONTGOMRY ST	JCT ST 33
10	S240510WCMHDNBI	US 5 SB	JCT I-91
11	S24050120MHDNBI	ST 83 NB RAMP Z	AT JCT I-91
12	C060364L8MTANBI	I 90 WB	.2 MI N. US 20 J1
13	C060364L7MTANBI	I 90 EB	.2 MI N. US 20 J1
14	M220364LUMTANBI	I 90 WB	.4MI.S.US20 K16
15	M220364LTMTANBI	I 90 EB	.4MI.S.US20 K16
16	M220384LPMTANBI	I 90 RAMPS INT 11	.5MI.S.ST122 K18
17	G080294LJMTANBI	HWY BRIGHAM HILL	.2MI.S.ST122 K22
18	N210141MJMHDNBI	ST146 NB	100 FT NORTH OF SUTTON TL
19	U020411MUMHDNBI	ST146 NB	1.6MI.NTH.OF ST-16