




## Structurally Deficient Bridges on the National Highway System New Jersey - Congressional District 11



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 175 structurally deficient NHS bridges in New Jersey, 9 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	2108162	ROUTE US 46	0.15 MI EAST OF C.R RT604
2	1417152	US 206	9.7 MI N OF RT 202 JCT
3	1412168	RT I-80 EASTBOUND	1.90 M.W. OF ROCKAWAY R.
4	1412169	ROUTE I-80 WB	1.95 M.W. OF ROCKAWAY R.
5	1913154	NJ 15 NB	4.3 MILES SOUTH OF RT 94
6	1412172	I-80 WB	1.9 MI WEST OF RTE 15
7	1412171	I-80 EB	1.9 MI WEST OF RTE 15
8	1412174	RT.I-80 EASTBOUND	1.95 MI E OF EXIT 30 JCT
9	1464156	SALEM ST CO RD 665	1.2 MI SE OF US RT 46
10	1420157	ROUTE I-287 N.B.	RT. I-287 & 46 JCT.
11	1414168	I-80 & RAMP D	RT I-80 287 INTERSECTION
12	1405156	NJ ROUTE 23	4.13 MI N JCT 23 W/ I-287
13	1414177	I-80 RAMP B	RTE 280 INTERCHANGE
14	1402153	ROUTE 10	4.75 MILES EAST OF I-287
15	1418151	RT.I-280 EB	1.4 MI SE OF 280-80 JCT
16	728151	RT. I-280 WB	0.2 MI E OF 280-PSSC R JT
17	728150	I280 EB	0.2 MI E OF 280-PSSC R JT
18	728155	I280 EB	0.8 MI E OF 280-PSSC R JT
19	728159	I-280 EASTBOUND	.5 MI W.OF I-280 EXIT,5