




Structurally Deficient Bridges on the National Highway System Pennsylvania - Congressional District 04



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 591 structurally deficient NHS bridges in Pennsylvania, 66 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	40068003000000	MIDLAND ROAD	5000' EAST OF OHIO LINE
2	430060011000000	SR 60,NB/SB BEAVER	SHENANGO TOWNSHIP
3	370060002101700	BEAVER VALLEY EX	1/2 MI. NORTH OF SR 0422
4	370422025115610	BEN FRANKLIN HW	SR 0422 WB OVER SR 0060
5	370422025016680	BEN FRANKLIN HW	SR 0422 EB OVER SR 0060
6	40060023100000	BEAVER VALLEY EX	SR 0060 SB O/ TWP.RD.535
7	40060023000000	BEAVER VALLEY EX	SR 0060 NB O/TWP. RD. 535
8	370422028115160	BEN FRANKLIN HW	U.S.422,WB O/ TR 18
9	370422029000000	BENJ FRANKLIN HW	250' N.W.OF SR 0168
10	370422029100000	BENJ FRANKLIN HW	250'N.W.OF SR 0168
11	40060027126070	BEAVER VALLEY EX	1/4 MI. SOUTH OF SR 0051
12	370422034100000	BENJAMIN FRANKL HY	1 MI. WEST OF SR 0065
13	370422034000000	BENJAMIN FRANKL HW	1 MI. WEST OF SR 0065
14	40060009016350	BEAVER VALLEY EX	1.5 MI.N. OF 3016
15	40051026003800	PENNSYLVANIA AV	200' S.E. OF SR 4027
16	40060008100000	BEAVER VALLEY EX	600'N.OF ALIQ.INTERCH.
17	370422039011300	BENJAMIN FRANKLIN	SHENANGO TWP.OVER SR 2004
18	40060007121160	BEAVER VALLEY EX	TR60 SB O/GREENGARDEN RD.
19	40065005000000	OHIO RIVER BL	@ MERCHANT ST. EXTENTION
20	370422053001240	BENJAMIN FRANKL HW	3/4 MI. WEST OF SR 0019
21	20079066118010	RAYMOND P SHAFF HW	1016 SB OVER GLENFIELD RD
22	20079066016800	RAYMOND P SHAFF HW	1016 NB OVER GLENFIELD RD
23	20079069011600	RAYMOND P SHAFF HW	1 MI.NORTH OF SR 4022
24	20079069111850	RAYMOND P SHAFF HW	1 MI.NORTH OF SR4022
25	100079080415840	LR1021,SR0079	NORTH OF CRIDERS CORNER
26	20079073421090	RAYMOND P SHAFF HW	JUST N OF WEXFORD INTERCH
27	20079073518950	RAYMOND P SHAFF HW	JUST N OF WEXFORD INTERCH
28	20079075500000	RAYMOND P SHAFF HW	OVER SR 4052 (RED BELT)
29	20079075400000	RAYMOND P SHAFF HW	LR 1021 NB OVER LR 02271
30	20065010008160	OHIO RIVER BL	EMSWORTH BORO
31	20079076121180	RAYMOND P SHAFF HW	LR 1021 OVER PA TURNPIKE
32	20079076112800	RAYMOND P SHAFF HW	LR 1021 SB OVER LR 246 19
33	20079076010960	RAYMOND P SHAFF HW	LR 1021 NB OVER 246
34	20065009007450	OHIO RIVER BL	2 MI.S.E.OF SR 0079
35	20065006031080	OHIO RIVER BL	2.5 MI.S.E.OF SR 0079
36	24003015021630	MCKNIGHT RD	1/2 MI. N.W. OF SR 4070
37	24003015000000	MCKNIGHT RD	TRUCK RT.19 OVER SR 4070
38	20008030010950	WILLIAM FLYNN HW	600'SOUTH OF DUNCAN AVE.
39	20008031007450	WILLIAM FLYNN HW	.5 MI. SOUTH OF SR 1010
40	20008041011080	WM.FLYNN HW	@ INTERSECTION W/SR 0910
41	20028016000000	SR 28 NB	3/4 MI.WEST OF HIGH.PARK
42	20028027000000	SR 0028 SH	NEAR HARMARVILLE INT.
43	20028026021090	SR 0028 SH	NEAR HARMARVILLE INT.
44	20028026122630	SR 0028 SH	NEAR HARMARVILLE INT
45	20028027100000	SR 0028 SH	NEAR HARMARVILLE INTERCH
46	20028027110850	SR 0028 SH	HARMARVILLE INTERCHANGE
47	20028029113270	SR 0028 SH	SR 28 SB OVER TURNPIKE
48	20028029011120	SR 0028 SH	SR 28 NB OVER TURNPIKE
49	20028031117440	SR 0028 SH	LR 1037 SB OVER LR 02169

Bridge Label	Structure ID	Bridge Description	Location Description
50	100356005021430	SR0356 NB&SB	NOLF CORNERS
51	640356022200000	SR 0356	FREEPORT BRIDGE