




Structurally Deficient Bridges on the National Highway System



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2005, all data is from the 2007 NBI. Of the 591 structurally deficient NHS bridges in Pennsylvania, 65 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	190080233000000	I 80	2 MILES EAST OF BUCKHORN
2	400081147408190	SR 0081 I-81 NB	BUTLER TWP 2 M N TR 93
3	400029007000000	SR0029 TR 29 NB&SB	HANOVER TWP 1 M S SR 2002
4	400081154508810	SR 0081 I-81 SB	DORRANCE TWP OVER SR 3007
5	400011055400000	SR 0011 TR 11	LARKSVLE BO 1 M E SR 1004
6	400080271512030	SR 0080 I-80 WB	WHITE HAVEN B .5M W TR940
7	400080271409740	SR 0080 I-80 EB	WHITE HAVN BO .5M W TR940
8	400081173521850	SR 0081 I-81 SB	LAFLIN BORO .6 M S EX#175
9	400011079016100	SR 0011 TR 11	DUPONT BORO JCT TR 315
10	400081177120090	SR 0081 I-81 SB	DUPONT BORO .2 M S EX 178
11	400081177020880	SR 0081 I-81 NB	DUPONT BORO .2 M S EX 178
12	357410131401020	MAIN ST BR NO 2	MOOSIC BORO W OF PARK STR
13	350081179103270	SR 0081 I-81 SB	MOOSIC BORO .2 M S TR 502
14	350081179011640	SR 0081 I-81 NB	MOOSIC BORO OVER TR 502
15	350081183116290	SR 0081 I-81 SB	SCRANTON CTY 2M N SR 3016
16	350081183022670	SR 0081 I-81 NB	SCRANTON CTY 2M N SR 3016
17	350081189423800	SR 0081 I-81	SCRANTON OVER RR&LACK RVR
18	450080283101110	I-80 WB(LR 1009)	AT CARBON CO.LINE
19	450080283001000	I-80 EB (LR 1009)	E.OF CARBON CO. LINE
20	450209029000000	US 209 & PA 33	S.END OF SNYDERSVIL RAMPS
21	450033018013610	SR 33 (LR796)	0.4 MI.S. OF I-80