




Structurally Deficient Bridges on the National Highway System Alabama - Congressional District 01



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 108 structurally deficient NHS bridges in Alabama, 9 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	2319	US. 45 & S.R. 17	4.9MI.N.OF MOBILE CO. LN.
2	2320	US. 45 & S.R. 17	5.4MI.N. OF MOBILE CO. LN
3	13791	US 98	4.5 MI W I-65
4	8134	I-10 EB	I10 @ US 90 INTERCHANGE
5	8133	I-10 WB	I-10 @ US 90
6	15302	I-10 WB & EB	2.2 MI E US 90
7	9444	SR 158	0.50 MI E US 45
8	8961	I-10 WB & EB	3.3 MI E JCT SR 163
9	8138	I-10 WB & EB	3 MI E US 90
10	1918	U.S.43	2.1 MI. S. OF WAGARVILLE
11	1917	U.S.43	4.7 MI. N. OF MCINTOSH
12	1739	U.S.43	3.4 MI. N. OF CALVERT
13	8560	I-65	1 MI N SR 287
14	11677	SR 59	0.1 MI S CO RD 12
15	8184	I-65	1.1 MI S JCT SR 21
16	6479	I-65	3.4 MI N JCT SR 21
17	3033	U.S.84	2 MI. W. OF REPTON
18	6827	I-65	4 MI S SR 41