




Structurally Deficient Bridges on the National Highway System Arizona - Congressional District 01



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 26 structurally deficient NHS bridges in Arizona, 1 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	457	I 40; WB	3.72 mi W Jct SR 89
2	385	SR 69;FAP 029	At Jct SR 89
3	505	I 17; SB	0.6 mi N Jct SR 260
4	654	I 17; SB	6.1 mi N Jct SR 260
5	653	I 17; NB	6.1 mi N of Jct SR 260
6	532	IRR US 89; FAP 037	1.53 mi N Jct SR 64
7	582	IRR US 89; FAP 037	1.1 mi North Jct US 160
8	321	I 40; EB	20.7 mi West Jct SR 99
9	459	I 40; WB	14.8 mi W Jct SR 77
10	280	SR 77	9.8 mi N Jct SR 277
11	278	SR 77	5.5 mi N Jct SR 277
12	181	US 60	12.7 mi E Jct US 180