



## Structurally Deficient Bridges on the National Highway System California - Congressional District 24



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 1030 structurally deficient NHS bridges in California, 54 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	51 0237L	STATE ROUTE 1	05-SB-001-M33.1
2	51 0120L	ROUTE 135	05-SB-135-R10
3	51 0120R	ROUTE 135	05-SB-135-R10
4	51 0071L	ROUTE 101 SB	05-SB-101-84.34
5	51 0071R	ROUTE 101 NB	05-SB-101-84.34
6	51 0150	STATE ROUTE 1	05-SB-001-R4.38
7	51 0073L	ROUTE 101	05-SB-101-70.91
8	51 0240R	STATE ROUTE 1	05-SB-001-R.16
9	51 0018L	U.S. HIGHWAY 101	05-SB-101-56.00
10	52 0017R	US 101 NB	07-VEN-101-R24.34-VEN
11	52 0267L	STATE ROUTE 126	07-VEN-126-R12.71-SPA
12	52 0267R	STATE ROUTE 126	07-VEN-126-R12.70-SPA
13	52 0183	STATE ROUTE 126	07-VEN-126-19.26
14	52 0317F	RTE 23	07-VEN-023-R3.34-THOK