




Structurally Deficient Bridges on the National Highway System



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode data from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2005, all data is from the 2007 NBI. Of the 136 structurally deficient NHS bridges in Colorado, 74 could not be geocoded because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	C-15-J	US 34 ML	1.5 MI E OF ESTES PARK
2	C-15-AI	US 34 ML	7 MI W OF LOVELAND
3	B-16-AE	US 287 ML	0.9 MI N OF JCT SH 1
4	B-16-D	SH 14 ML	1 MI E OF JCT US 287
5	D-16-K	SH 119 N/EBND	1.1 MI W OF JCT I-25
6	C-17-G	I 25 SERVICE RD	1.8 MI NO OF JCT SH 60 WE
7	C-18-N	US 85 ML NBND	5 MI NO OF JCT SH 256
8	C-18-AV	US 34 ML EBND	IN GREELEY
9	G-22-BB	SH 71 ML	0.5 MI N OF JCT US 24
10	C-23-E	I 76 ML WBND	14 MI SW OF STERLING EXIT
11	C-23-F	I 76 ML EBND	14 MI S.W. OF STERLING EX
12	I-25-L	US 40 ML	0.7 MI E OF KIT CARSON
13	L-26-H	US 50 EBND	In Lamar
14	L-27-M	US 50 ML	2.8 EAST OF GRANADA
15	G-28-F	I 70 ML WBND	11.4 MI. W. OF COLO.-KANS
16	L-28-C	US 50 ML	3 MI EAST OF GRANADA