




Structurally Deficient Bridges on the National Highway System



Consult your state DOT for the most up-to-date status of bridges.



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2005, all data is from the 2007 NBI. Of the 136 structurally deficient NHS bridges in Colorado, 14 could not be geocoded because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges related were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	F-16-GW	US 285 ML	0.3 MI E OF JCT SH 8
2	F-16-GR	US 285 ML	0.9 MI E OF JCT SH 8
3	F-16-F	US 85 ML NBND	IN LITTLETON
4	G-16-C	US 85 ML	4.7 MI N.W. OF SEDALIA
5	H-17-CH	I 25 ML NBND	8.5 MI N OF EL PASO-DOUGL
6	F-17-DM	SH 88 ML/ARAP RD	0.6 MI W OF SH 83
7	F-20-C	I 70 SERVICE RD	4.4 MI E OF JCT US 36 (BY
8	F-20-BR	I 70 ML EBND	1.1 MI E OF ARAPAHOE CL.
9	F-20-BQ	I 70 ML WBND	6.8 MI W OF AGATE SPUR
10	F-21-T	I 70 ML EBND	8.4 MI E OF JCT DEERTRAIL
11	F-21-S	I 70 ML WBND	3.6 MI W OF JCT AGATE SPU
12	G-21-Y	I 70 BUSINESS SPUR	7.9 MI E ARAPAHOE-ELBERT
13	G-21-B	I 70 FRONTAGE RD	1.0 MI E OF JCT I70-A