




Structurally Deficient Bridges on the National Highway System Connecticut - Congressional District 05



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 66 structurally deficient NHS bridges in Connecticut, 2 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	964	US ROUTE 44	DOWNTOWN SALISBURY
2	548	I-84 TR 803	RAMP 7 SB TO I84 EB
3	4256	INTERSTATE-84 WB	.17 MI W OF HOUSATONIC RV
4	4255	INTERSTATE-84 EB	.17 MI WEST-HOUSATONIC RV
5	908	US ROUTE 202	.75 MI E OF JCT RTE 63
6	609	ROUTE 8 SOUTHBOUND	1.5 MILE SOUTH OF RTE 118
7	606	ROUTE 8 SOUTHBOUND	EXIT 41 OFF ROUTE 8
8	604	ROUTE 8 NORTHBOUND	0.9 MI S LITCHFIELD TL
9	03191A	INTERSTATE-84 EB	I-84 EXIT 20
10	03190C	I-84 TR 811	NB RTE 8 TO EB 84 EXIT 31
11	03190D	I-84 TR 812	EXIT 19, 84 WB TO 8 SB
12	471	US ROUTE 6	JCT OF RT 6 & RT 72
13	3320	I-84 TR 816	EXIT 6 ON ROUTE 72 WB
14	2069	INTERSTATE-691 WB	AT LEWIS AVE EXIT