




Structurally Deficient Bridges on the National Highway System Hawaii - Congressional District 01



Consult your state DOT for the most up-to-date status of bridges.



Area of Detail



Note: The bridges displayed on this map represent the results of a combined ITS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 32 structurally deficient NHS bridges in Hawaii, 9 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	003000H20100624	FAI-H2(O.B.)	0.97MI N/MEHEULA PKWY BR
2	003000H20100625	FAI-H2(I.B.)	0.97MI N/MEHEULA PKWY BR
3	3000990401724	KAM HWY	0.08MI S/RAMP E
4	003000H10202075	HALONA ST	0.29MI E/HOUGHTAILING ST
5	3000920400796	ALA MOANA BLVD	0.12MI W/PIIKOI ST.
6	003000H10202513	SOUTH KING ST	0.10MI E/OLD WAIALAE RD