




Structurally Deficient Bridges on the National Highway System Illinois - Congressional District 01



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 297 structurally deficient NHS bridges in Illinois, 7 could not be geocoded because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	16240027599	ILL43 HARLEM AVE	0.2 M S 143RD P3
2	16042104129	ILL50 CICERO AVE	0.6 M N ILL 83 P26
3	16984403954	I-294 SB	0.5 M S 127TH P26
4	16984503955	I-294 NB	0.5 M S 127TH P26
5	16984803958	I-294 SB	1.3 M SE ILL 50 P26
6	16984903959	I-294 NB	1.3 M SE ILL 50 P26
7	16985003960	I-294 SB	1.7 M SE 127ST P3
8	16985103961	I-294 NB	1.7 M SE ILL 50 P3
9	16985203962	I-294 NB	1.6 M NW IL 83 P3
10	16985303963	I-294 SB	1.6 M NW IL 83 P3
11	16985403964	I-294 SB	1.5 M NW IL 83 P3
12	16985503965	I-294 NB	1.5 M NW IL 83 P3
13	16985603966	I-294 SB	0.8 M NE ILL 83 P3
14	16985703967	I-294 NB	0.8 M NE ILL 83 P3
15	16985803968	I-294 NB	0.6 M NE ILL 83 P3
16	16985903969	I-294 SB	0.6 M NW ILL 83 P3
17	16986103971	I-294 NB	0.7 M NW I55 P3
18	16109626232	I-57 SB	.6M S IL.83,SIBLEY B
19	16643904151	I-90 SKYWAY	0.4 M E I94 P7C