




Structurally Deficient Bridges on the National Highway System Illinois - Congressional District 09



Consult your state DOT for the most up-to-date status of bridges.



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 297 structurally deficient NHS bridges in Illinois, 7 could not be geocoded because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	16050804185	I-190 EB JFK	3.2 M W ILL 43 P9
2	16050904186	I-190 WB JFK	3.2 M W ILL 43 P9
3	16977103880	I-294 SB	1.2 M N ILL 72 P11
4	16977003879	I-294 SB	1 M S ILL 62 P11
5	16976403873	I-294 NB	0.7 M S US 14 P11
6	16071304349	TOUHY AVE	1.5 M N US 14 P13
7	16618304014	LAKE SHORE DRIVE	4800 N & 700 W
8	16618404015	LAKE SHORE DRIVE	4600 N & 732 W