




Structurally Deficient Bridges on the National Highway System Illinois - Congressional District 10



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 297 structurally deficient NHS bridges in Illinois, 7 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	49002711214	ILL 21	0.5 M N OF ILL 137
2	49992011176	I-94 NB	I94 1.3M S ILL 132
3	49990411237	ILL 120 WB	1.6 M W OF US 41
4	49990311236	ILL 120 EB	1.6 M W OF US 41
5	49000711192	ILL 21 & US 45	1.0 M N OF LAKE-COOK
6	16024204006	ILL21 MILWAUKEE	0.3 SE US 45 P14
7	16053104205	WILLOW RD	2.4 M S ILL 68 P14
8	16024304007	ILL 21 MILWAUKEE	0.7 SE I294 P14
9	16054604221	LAKE COOK RD	0.6 M W ILL 43 P1
10	16053304206	WILLOW RD	1 M W ILL 43 P14
11	49008811292	DEERFIELD RD	0.2 M E OF US 41
12	16973903799	I-94 WB	0.2 M W US 41 P14
13	16053504208	WILLOW RD	1 M E ILL 43 P14