




Structurally Deficient Bridges on the National Highway System Illinois - Congressional District 14



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



● Deficient Bridges

○ City

— Interstate Highway

— Other NHS Highway

— Body of Water

— Urbanized Areas

— 14th Congressional District



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 297 structurally deficient NHS bridges in Illinois, 7 could not be geocoded because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	52002611933	ILL ROUTE 26	2.5 MI S AMBOY RD
2	52002511932	ILL ROUTE 26	.5 MI S AMBOY RD
3	19990823177	I-88 EB	W EDGE OF DEKALB
4	45008208834	ILL 47	5 MI N OF IL 56
5	45002710332	ILL 56 WB	.4M N OF GALENA BLVD
6	45002610331	ILL 56 EB	.4M N OF GALENA BLVD
7	47003210821	US 30	0.5 MI W OF US 34