




Structurally Deficient Bridges on the National Highway System Illinois - Congressional District 16



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 297 structurally deficient NHS bridges in Illinois, 7 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	43000323765	US 20 WB	3.8 MI E JCT ILL 35
2	43000409986	US20 EB	4.8 MI W JCT ILL84
3	43000509987	US20 WB	4.8 MI W JCT ILL84
4	43000709989	US 20 EB	2.0 MI W JCT ILL84
5	43003813018	ILL RT 84	2.0 MI S. HANOVER
6	8001601773	ILL 84	2 MI N SAVANNA
7	98002121471	ILL RT 84	0.9 MI S JCT US 30
8	98005325842	US 30	NW EDGE MORRISON
9	89000319377	US 20	2 MI E OF ELEROY
10	71001016091	ILL 26	1.0 MI S JCT US 52
11	101005200222	US 20 EB	1 MI W OF ILL 2
12	101005100221	US 20 WB	1 MI W OF ILL 2
13	101005400224	US 20 W B	0.8 MI W OF ILL 2
14	101005300223	US 20 E B	0.8 MI W OF ILL 2
15	101005600227	US 20 W B	1 MI S OF ROCKFORD
16	101005500226	US 20 E B	1 MI S OF ROCKFORD
17	101613526070	JEFFERSON ST	0.1 MI E OF N MAIN
18	101006500236	US 20 E B	S EDGE ROCKFORD
19	101006600237	US 20 W B	S EDGE ROCKFORD
20	4000901133	ILL 173	2.0 MI E POPLAR GROV
21	56002813135	ILL 173	2.0 E OF CO LINE