




Structurally Deficient Bridges on the National Highway System Illinois - Congressional District 19



Consult your state DOT for the most up-to-date status of bridges.



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 297 structurally deficient NHS bridges in Illinois, 7 could not be geocoded because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	42000109873	US 67	1.7 M N JERSEYVILLE
2	60010914340	ILL 4	.71 MI N US 40
3	84002818380	6TH ST / BL 55 (NB	.25M S I-72
4	61000214605	FAP-322 (US-51)	1.5 MI S VERNON
5	26003806219	FAP-322 (US-51)	4 MI S US-40
6	26003706218	FAP-322 (US-51)	3.5 MI S US-40
7	61003614680	FAP-327 (US-50)	E UP RR IN SALEM
8	25001005968	FAI-70 WB	8.8 MI E ALTAMNT INT
9	25000905967	FAI-70 EB	8.8 MI E ALTAMNT INT
10	13000503099	FAP-327 (US-50)	.75 MI W RICHLAND CL
11	51000711739	FAP-332 (ILL-1)	2 MI S LAWRENCEVILLE