



 Deficient Bridges
 City
 Interstate Highway
 Other NHS Highway
 Body of Water
 Urbanized Areas
 11th Congressional District



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2005, all data is from the 2007 NBI. Of the 108 structurally deficient NHS bridges in Indiana, 3 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	40900	I-69 SBL	0.55 S SR 127
2	40890	I-69 NBL	0.55 S SR 127
3	40950	I-69 SBL	0.14 S SR 120
4	40940	I-69 NBL	0.14 S SR 120