




Structurally Deficient Bridges on the National Highway System Indiana - Congressional District 08



Consult your state DOT for the most up-to-date status of bridges.



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 108 structurally deficient NHS bridges in Indiana, 3 could not be geocoded because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	41050	I-70 EBL	2.95 W US 41
2	41060	I-70 WBL	2.95 W US 41
3	22750	SR 63 NBL	1.53 S US 136
4	22735	SR 63 SBL	0.62 N SR 234
5	41090	I-70 EBL	1.43 W US 41
6	41100	I-70 WBL	1.43 W US 41
7	41110	I-70 EBL	0.83 W US 41
8	41120	I-70 WBL	0.83 W US 41
9	22805	SR 63 SBL	1.99 S SR 28
10	22685	SR 63 SBL TO US 36	0.39 N US 36
11	41150	I-70 EBL	0.38 E US 41
12	41160	I-70 WBL	0.38 E US 41
13	41180	I-70 WBL	0.57 E US 41
14	41170	I-70 EBL	0.57 E US 41
15	41220	I-70 WBL	1.40 E US 41
16	41210	I-70 EBL	1.40 E US 41
17	41230	I-70 EBL	1.88 E US 41
18	41240	I-70 WBL	1.88 E US 41
19	41250	I-70 EBL	2.09 E US 41
20	16710	US 231	0.94 MILE NORTH SR 56