




Structurally Deficient Bridges on the National Highway System Louisiana - Congressional District 02



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 90 structurally deficient NHS bridges in Louisiana, 3 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	22600051001312	US0090	2260051001312
2	22600051002552	US0090	2260051002552
3	22600051005871	US0090	US0090
4	22600060100001	US0090	US0090
5	22604230100481	LA3046	LA3046
6	23604300200001	LA3139	5.07 MI E OF HICKORY AVE.
7	23604509002168	I0010	2364509002168
8	23600070101061	US0061	US0061
9	23604509003422	I0010	2364509003422
10	23604509004193	US0090	I0010
11	23604509005228	I0010	I0010
12	23604509005217	I0010	2364509005217
13	23604509005676	I0010	I0010
14	23604503404236	I0610	2364503404236
15	23600463101202	LA0039	LA0039
16	23600460202211	LA0046	2360460202211
17	23600460202341	LA0046	2360460202341
18	23604501700002	I0010	I0010
19	23604501700001	I0010	I0010