



Structurally Deficient Bridges on the National Highway System Maryland - Congressional District 02



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 47 structurally deficient NHS bridges in Maryland, 4 could not be geocoded because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	10000020118010	IS 895B RAMP	0.55 MILE SOUTH OF MD 695
2	10000030183010	IS 95 SBR	0.90 MILE NORTH OF MD 588
3	300000B-X670013	MD RTE 43 EB	0.57 MI W OF MD RTE 7