




Structurally Deficient Bridges on the National Highway System Michigan - Congressional District 08



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 261 structurally deficient NHS bridges in Michigan, 15 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	33133061000B010	M-43 EB	IN LANSING (SAGINAW ST)
2	19119031000B010	US-127	5.3 MI N OF INGHAM CO LIN
3	19119081000R020	US-127 NB	0.2 MI N OF INGHAM CO L
4	33133084000S030	SB I-496 TO EB 96	@ I-496 SB (RAMP C)
5	33133031000R012	US-127 SB	0.3 MI N OF JACKSON CO LI
6	33133031000R011	US-127 NB	0.3 MI N OF JACKSON CO LI
7	47147065000S140	I-96 WB	@ US-23
8	47147013000S031	US-23 NB	1.8 MI N OF M-36
9	47147064000S060	US-23 NB	@ US-23
10	47147014000S021	US-23 NB	4.1 MI N OF I-96
11	63163172000S150	I-75 SB	1.1 MI SE OF M-15