



Structurally Deficient Bridges on the National Highway System Michigan - Congressional District 12



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 261 structurally deficient NHS bridges in Michigan, 15 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	63163101000S140	US-24 N TO M-10 W	IN SOUTHFIELD (I-696)
2	63163081000B020	M-10 NB	IN SOUTHFIELD
3	82182112000S340	M-102 RAMP	N LTS OF DETROIT
4	82182112000S348	M-102	IN DETROIT
5	63163174000S052	I-75 SB	N LTS OF MADISON HTS
6	63163174000S051	I-75 NB	N LTS OF MADISON HTS
7	63163103000S050	I-696	IN ROYAL OAK
8	63163103000S090	I-696 RAMPS GH&GD	IN MADISON HTS
9	63163103000S070	I-696 RAMPS AF&EF	IN MADISON HTS
10	50150061000S330	RAMPS E&F	CITY OF WARREN
11	50150061000S080	RAMP G AT MOUND RD	CITY OF WARREN
12	50150062000S080	I-696 RAMP E TO N	@ ROSEVILLE & ST CLAIR SH
13	50150111000S110	11 MI RD/TRM I-696	W LTS OF ST CLAIR SHORES
14	50150062000S110	I-696 RAMP N TO W	IN ST. CLAIR SHORES
15	50150051000B010	M-3 SB	IN MT CLEMENS
16	50150051000B020	M-3 NB	IN MT CLEMENS