




Structurally Deficient Bridges on the National Highway System Minnesota - Congressional District 05



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



- Deficient Bridges
- City
- Interstate Highway
- Other NHS Highway
- Body of Water
- Urbanized Areas
- 11th Congressional District



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 47 structurally deficient NHS bridges in Minnesota, 1 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	5462	TH 7 (CSAH 25)	AT JCT TH 100 & 7
2	27932	TH 62 EB	AT THE W JCT TH 62 & 35W
3	27937	TH 62 WB	AT THE E JCT TH 62 & 35W
4	27941	I 35W SB off ramp	At E Jct of TH 62 & 35W
5	27939	I 35W SB	0.2 Mi North of East Jct
6	27940	I 35W NB	0.2 Mi North of East Jct
7	27871	I 35W SB	0.7 MI S OF JCT TH 94
8	27842	I 94 WB on ramp	At the Jct TH 65 & 94
9	27861	I 94 WB off ramp	0.1 MI E OF JCT TH 55
10	9340	I 35W	1.0 MI NE OF JCT TH 94