




Structurally Deficient Bridges on the National Highway System Minnesota - Congressional District 06



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 47 structurally deficient NHS bridges in Minnesota, 1 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	9086	TH 23	1.3 MI W OF JCT TH 10
2	3622	US 12	0.1 MI E OF JCT CSAH 30
3	86813	I 94 WB	1.9 MI E OF JCT TH 25
4	86814	I 94 EB	1.9 MI E OF JCT TH 25
5	4654	TH 36	at Wisconsin state line
6	9115	TH 36 EB	AT JCT TH 95