




Structurally Deficient Bridges on the National Highway System North Carolina - Congressional District 02



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail

Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 160 structurally deficient NHS bridges in North Carolina, 7 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	510051	US401BUS.	0.2 MI N JCT NC 24
2	510112	US401BUS.	0.2 MI.S.JCT.SR2311
3	510125	NC24	0.3 MI.E.JCT.US401BUS.
4	510061	I95BUS.LOOP&US301	0.1 MI.N.JCT.NC24&NC87
5	510085	I95BUS.LOO	0.5MI.N.JCT.NC24&NC2
6	1810004	US1BYP.NBL	0.5 MI. S. OF SR1115
7	1010100	I95	1.8MI.N.JCT.I95,US301&701
8	1630039	US421/S.B.L.	1.2 MI N. JCT. SR1227
9	1630056	NC24	0.9MI.E.JCT.SR1920
10	1010097	US70 EBL	0.3MI E.JCT US70A
11	1010116	I95 SBL	0.4 MI.N.JCT.SR2339
12	1010114	I95 NBL	0.4MI.N.JCT.SR2339
13	1010119	I95 SBL	0.3 MI.S.JCT.US301
14	1010118	I95 NBL	0.3 MI S JCT US 301
15	1010122	I95	0.22 MI.E.JCT.SR2159
16	830012	I95 NBL	2.5 MI S JCT NC481