




Structurally Deficient Bridges on the National Highway System



Consult your state DOT for the most up-to-date status of bridges.



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2005, all data is from the 2007 NBI. Of the 160 structurally deficient NHS bridges in North Carolina, 7 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	110002	US321	50 FT.E.JCT.SR1314
2	1710013	I77 SBL	0.07 MI.S.JCT.NC268
3	670055	US421 NBL	1.1 MI. W. JCT. SR1300
4	1710122	US52NBL	1.5 MI.N.JCT.NC268
5	590086	I40 WBL	1.3 MI. E. JCT. NC801
6	590085	I40 EBL	1.3 MI. E. JCT. NC801
7	1690029	US52 NBL	2.0 MI. N. JCT. SR1102
8	1690030	US52 SBL	2.0 MI. N. JCT. SR1102
9	670222	US421 NBL	0.4 MI. W. JCT. SR1140
10	670335	US52 SBL	1.5 MI. N. JCT. SR16
11	670319	US52 NBL	1.5 MI. N. JCT. SR1632
12	670246	US421	0.1 MI.W.JCT.I40
13	670351	I40 BUS RAMPS	NW QUAD. I40BUS & NC67
14	670369	I40BUS & US421 WBL	0.3 MI. E. JCT. NC66&150