




Structurally Deficient Bridges on the National Highway System



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2005, all data is from the 2007 NBI. Of the 160 structurally deficient NHS bridges in North Carolina, 7 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	1590137	I85	1.0 MI. S. JCT. NC150
2	1590003	NC49 NBL	2.4 MI. W. JCT. NC8
3	1510026	I85 SBL	3.1 MI. S. JCT. US311
4	1510020	I85 NBL	3.1 MI. S. JCT. US311
5	1510033	US64	0.2 MI. W. JCT. SR1409
6	1510466	I85 NBL	0.9 MI. S. JCT. US311
7	1510467	I85 SBL	0.9 MI. S. JCT. US311
8	810324	US220	2.0 MI. N. JCT. SR2313
9	810317	US220	1.5 MI. N. JCT. NC150
10	810313	US220	1.65 MI. S. JCT. NC150
11	810307	US220	1.85 MI. S. JCT. NC150
12	1510236	US220 SBL	2.8 MI. N. JCT. US311
13	1510235	US220 NBL	2.8 MI. N. JCT. US311
14	1510173	US64	0.06 MI. W. JCT. SR2912
15	810277	US421 SBL	3.3 MI. N. JCT. NC62
16	1510082	US421 SBL	4.5 MI. W. JCT. NC49
17	810380	I40 & I85	0.6 MI. N. JCT. SR3055