




Structurally Deficient Bridges on the National Highway System



Consult your state DOT for the most up-to-date status of bridges.



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2005, all data is from the 2007 NBI. Of the 160 structurally deficient NHS bridges in North Carolina, 7 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	1550107	I95 SBL	1.2 MI.N.JCT.SR2455
2	1550106	I95 NBL	1.2 MI.N.JCT.SR2455
3	470005	US76	0.3 MI.E.JCT.SR1355
4	1550158	I95 SBL	0.6 MI.S.JCT.NC20
5	510226	SR1007	0.2 MI.N.JCT.US401BUS.
6	510022	NC59	0.5 MI W JCT SR 2274
7	510077	I95 NBL	0.4 MI.S.JCT.SR2341
8	510111	I95 SBL	0.3MI N JCT SR 2337
9	510109	I95 NBL	0.3 MI.N.JCT.SR2337
10	470056	US76 WBL	0.5MI.W.JCT. SR1005
11	470052	US74/US76BYP WBL	0.4MI W.JCT US701 BUS
12	470051	US74/US76BYP EBL	0.4 MI.W.JCT.701BUS
13	190079	US17	0.1 MI N JCT NC87
14	190036	US74/US76 WBL	1.7 MI.E JCT SR1417
15	190108	US17,74,76(SBL)	1.0 MI.N.JCT.NC133
16	190107	US17,74,76	1.0MI.N.JCT.NC133
17	190007	US421SB/NC133NB	1.9MI N OF JCT NC 133
18	1290029	NC133	1.5 MI.N.US421
19	1290030	US421	6.0 MI S JCT NC 132
20	1290008	US117/NC132 SBL	0.33 MI. S. OF SR2123
21	1290014	US74 & 76	0.2MI.W. OF SR1411
22	1290012	US74&76	0.8 MI. E. JCT. SR1417