




Structurally Deficient Bridges on the National Highway System



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail:



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode data from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2005, all data is from the 2007 NBI. Of the 160 structurally deficient NHS bridges in North Carolina, 7 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	250018	I85 SBL	0.7 MI. S. JCT. SR1438
2	250011	I85 NBL	0.7 MI. S. JCT. SR1438
3	250086	I85 NBL	1.2 MI.N.JCT.NC73
4	250088	I85 SBL	1.2 MI. N. JCT. NC73
5	250134	I85,US601 NBL	0.3 MI. S. JCT. SR2114
6	250103	NC49	0.6 MI. W. JCT. SR2423
7	1670024	NC49	0.6 MI.S.JCT.SR1617
8	70033	US74 WBL	1.0 MI.E.JCT.NC218
9	70070	US52	0.5 MI. N. JCT. SR1627
10	70056	US52	0.1 MI. N. JCT. SR1649
11	1530003	US1	0.1 MI. S. JCT. SR1999
12	1530016	US220	0.1 MI. S. JCT. US74
13	1650097	US74 EBL	2.0 MI. E. JCT. SR1369
14	510116	NC24/NC87/NC210	0.08 MI.E.JCT.BRAGG BLVD.