




Structurally Deficient Bridges on the National Highway System North Carolina - Congressional District 10



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 160 structurally deficient NHS bridges in North Carolina, 7 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	230140	I40 EBL	.45 MI.E.JCT.SR1924
2	230149	I40 EBL	.2 MI.N.JCT.SR1815
3	270367	US321 SBL	.15 MI.S.JCT.SR1760
4	350036	I40	0.6 MI. W. JCT. UN19