




Structurally Deficient Bridges on the National Highway System North Carolina - Congressional District 11



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 160 structurally deficient NHS bridges in North Carolina, 7 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	1730003	US19,74	50 FT.N.JCT.SR1101
2	990145	US23,74	.1 MI.S.JCT.SR1538
3	870142	I40	.1 MI.E.JCT.SR1338
4	870155	US23,74 NBL	.1 MI.S.JCT.US19,23
5	870158	US23,74 SBL	.1 MI.S.JCT.US19,23
6	870168	US23,74 SBL	.6 MI.S.JCT.NC209 CONN.
7	870073	SR1660	1.0 MI.S.JCT.I40
8	870095	SR1660	.3 MI.N.JCT.US19,23,74
9	210345	US19,23 NBL	.8 MI.S.JCT.SR1740
10	210353	US19,23 NBL	0.65 MI.S.JCT.SR1720
11	890212	I26,US74 EBL	1 MI.W.JCT.US64
12	1110017	US221	.6 MI.S.JCT.SR1786