




Structurally Deficient Bridges on the National Highway System



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2005, all data is from the 2007 NBI. Of the 160 structurally deficient NHS bridges in North Carolina, 7 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	1190215	I77 RAMP	0.15 MI. N. JCT. NC160
2	570022	I85 SBL	0.8 MI. S. JCT. NC150
3	570018	I85 NBL	0.8 MI. S. JCT. NC150
4	570041	I85 SBL	0.7 MI. S. JCT. NC150
5	570118	US29&70/I85BUS.LP.	0.8 MI. N. JCT. NC8
6	670297	US52 NBL	0.3 MI. N. JCT. SR1669
7	570039	US64 EBL&RAMP WBL	1.1 MI. S. JCT. NC8
8	670267	US52 NBL	0.7 MI. N. JCT. SR2264
9	670268	US52 SBL	0.7 MI. N. JCT. SR2264
10	670312	I40 BUS	0.7 MI. W. JCT. US52
11	670257	US52 SBL	0.9 MI. S. JCT. SR2264
12	670256	US52 NBL	0.9 MI. S. JCT. SR2264
13	670253	US52	0.3 MI. S. JCT. SR2456
14	670255	US52	0.2 MI. S. JCT. SR2456
15	670078	US52, US311,NC8	0.6 MI. S. JCT. SR3875
16	670115	US52, US311 & NC8	0.6 MI. N. JCT. I40
17	810336	I40 & US220 EBL	0.25 MI. W. JCT. SR1007
18	810291	I40 & I85 WBL RAMP	0.2 MI. N. JCT. US421
19	810349	I40,I85 WBL	0.3 MI. N. JCT. SR1401