




Structurally Deficient Bridges on the National Highway System Nebraska - Congressional District 01



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 39 structurally deficient NHS bridges in Nebraska, 0 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	S275 06673	US275	8E MEADOW GROVE
2	S275 07005	US275	5W NORFOLK
3	S275 07202	US275	3W NORFOLK
4	S020 38797	US20	3W LAUREL
5	S020 39662	US20	5NE LAUREL
6	S030 40004	US30	4E SCHUYLER
7	S020 40463	US20	13NE LAUREL
8	S275 10468	US275	2SE WISNER
9	S275 11475	US275	2NW WEST POINT
10	S080 40105	SB-I180/US34	I80/I180 INTRCHG
11	S080 40106	NB-I180/US34	I80/I180 INTRCHG
12	U142503445	WEST O/FAU 5266	WEST O ST @ 7TH ST
13	S275 13258	US275/N91	2SE SCRIBNER
14	S035 05800	N35	2SW HUBBARD
15	S080 40977L	I80	WAVERLY INTRCHG
16	S080 40977R	I80	WAVERLY INTRCHG
17	S077 09791	US77/N92	5NE WAHOO
18	S077 12541	US77	US77/US275 INTRCHG
19	S077 12546	US77	1S WINSLOW
20	S077 16541	IRR/US77	5S WINNEBAGO
21	S075 07543L	SB-US75	3N PLATTSMOUTH
22	S075 07484	US75	3N PLATTSMOUTH
23	S034 38208	US34	2E PLATTSMOUTH