



Structurally Deficient Bridges on the National Highway System New Jersey - Congressional District 08



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 175 structurally deficient NHS bridges in New Jersey, 9 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	1604162	RT 23 NB & RAMP"1"	0.6 MI. NO. OF RT 46
2	1600140	PAT-HAM TPK(CR504)	EAST OF VALLEY RD(CR 681)
3	1606160	U.S. ROUTE 46	1.9 MILES WEST OF RT 3
4	361531A	NB ENT FR SER.AREA	1 MI S OF GSP & RT3 JCT
5	361558T	NB ENTRNCE 154RAMP	2.3 MILES SOUTH OF I80
6	1607161	MAIN AVENUE(CR601)	1.2 M.WEST OF GSP
7	1603156	RAMP 8 FROM NJ 21	0.4 MI NW OF 3-21 JCT
8	1601162	NJ RT 3	0.3 MI NW OF 3-21 JCT
9	1601163	NJ RT 3	0.2 MI NW OF 3-21 JCT
10	1601164	NJ ROUTE 3	RT 3,RT 21,PASSAIC R JCT