



Structurally Deficient Bridges on the National Highway System



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode data from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 227 structurally deficient NHS bridges in New York, 5 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	2230869	RTE 25	0.2 MI W JCT SH 25 & I278
2	2230250	RTE 908F	JCT MOSHOLU PKY+BRONX RIV
3	1067119	RTE 907H	1.4MI N I95+BX RIVER PKWY
4	1067099	RTE 907H	.4 MI N I95+BX RIVER PKWY
5	1055789	RTE I678	JCT I495+RTE 678
6	2075849	RTE 907F	.4 MI SW I95+HTCHSN R PKY
7	5521229	RTE I678	I678 OVER EAST RIVER
8	5521269	RTE I295	295I OVER EAST RIVER