



Structurally Deficient Bridges on the National Highway System New York - Congressional District 19



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 227 structurally deficient NHS bridges in New York, 5 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	1040660	RTE 209	IN DEERPARK
2	1013982	RTE 17	JCT RTE 17+WALLKILL R
3	1003190	RTE 6	JCT SH 94 & US6 / SH17
4	5514192	RTE I87	2.4 MI S JCT RTS I-87<210
5	5040519	RTE I87	JCT OF I87 & S H 207
6	5034919	RTE I87	JCT OF RTS 94 & I-87
7	1040129	RTE 987C	JCT RTE 202 + PIP
8	1005130	RTE 9	6.7 MI N JCT RTS 9+129
9	1005140	RTE 9	6.9 MI N JCT US 9 & SH129
10	1032571	RTE I84	INT RTS I84(WB)& TSP
11	1032572	RTE I84	INT RTS I84(EB) & TSP
12	1032621	RTE I84	2.2 MI E JCT RTS I84+I684
13	1032622	RTE I84	2.2 MI E JCT RTS I84+I684