




Structurally Deficient Bridges on the National Highway System New York - Congressional District 26



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 227 structurally deficient NHS bridges in New York, 5 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	1021500	RTE 31	2.1MI W JCT RTS 31A + 63
2	4443250	RTE 31	JCT BARGE C+RTE31 BKPT
3	1015710	RTE 20	0.2MI W JCT RTS 20 + 36
4	1069862	RTE I390	IN WEST SPARTA
5	1069861	RTE I390	IN WEST SPARTA
6	1062502	RTE 390	0.8MI S JCT ROL NB+104