




Structurally Deficient Bridges on the National Highway System



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 227 structurally deficient NHS bridges in New York, 5 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	5043982	RTE I190	JCT RT 266 + 324 N.B.
2	1044960	RTE I190	INT N16 ON I-290
3	1022680	RTE 33	2.9 MI NE JCT RTS 33 + 5
4	1049759	RTE 940K	.2 MI N JCT MT READ &SH31
5	1048729	RTE I490	JCT I490 + MT READ BLVD
6	1049789	RTE 940K	.5 MI S JCT MT READ&SH104
7	2256060	RTE 31	ROCHESTER SUBWAY BROAD ST
8	1026059	RTE 590	JCT ROL + RTE 286