




Structurally Deficient Bridges on the National Highway System Ohio - Congressional District 04



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 178 structurally deficient NHS bridges in Ohio, 7 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	7501625	IR-75	2.94MI.S.OF JCT. SR-47
2	4600363	USR-33	.29MI.NM. OF JCT. SR-117
3	3202194	US 68 SR 15	NO DATA
4	5901626	I-71	2.61 MI N OF SR95
5	7001142	US 30	.62 MILES EAST OF SR 39