




## Structurally Deficient Bridges on the National Highway System Ohio - Congressional District 18



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 17 structurally deficient NHS bridges in Ohio, 7 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	7100248	ROZELLE CREEK	3.70 MI S OF JCT SR 104
2	7100965	US 23	0.5MI S OF JCT SR 159
3	4503546	EB I-70	1 M E OF JCT SR 37
4	4501020	SR 16 & SR 79	.6 M E OF JCT SR13DA-NB
5	4501179	SR 16	.2 M E OF JCT SR 79
6	4501209	SR 16	.9 M E OF JCT SR 79
7	3700879	US-33	0.04M E OF JCT SR595
8	4501322	EB SR 16	5 M W OF JCT SR 146
9	4504321	I-70	1.5 M W OF JCT SR 668
10	4504534	WB I-70	1.3 M E OF JCT SR 668
11	4504569	EB I-70	1.3 M E OF JCT SR 668
12	6001866	RAMP K OVER 5TH ST	2.25 M E OF JCT US 40
13	6002943	I-70	2.4 M W OF JCT SR 93
14	7902794	IR 77	0.55 MI. S. OF US 250
15	3401022	US 22	0.11 MI W OF JCT SR 9
16	3401057	US 22	0.11 MI W OF JCT SR 9
17	702587	IR 70	.26 M W OF SR-9