



Structurally Deficient Bridges on the National Highway System Oregon - Congressional District 01



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 39 structurally deficient NHS bridges in Oregon, 13 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	06713 009 02870	US101(HWY009) SB	037 MI S CANNON BEACH JCT
2	06524 047 00707	US 26 (HWY 047)	071 MI SE CANNON BCH JCT
3	01831 047 01628	US 26 (HWY 047)	025 MI SE SUMMIT CST RNGE
4	02165 047 02173	US 26 (HWY 047)	001 MI NW JEWELL JCT
5	02673 047 04630	US 26 (HWY 047)	7.1 MI W HWY 37 JCT
6	02302 102 08194	OR 47 (HWY 102)	1.0 MI N BANKS
7	02046 02WC04892	HWY 2W CONN	WASH. STATE LINE
8	00191A02W 04074	HWY 2W	5.0 MI E RANIER