




## Structurally Deficient Bridges on the National Highway System Pennsylvania - Congressional District 17



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 591 structurally deficient NHS bridges in Pennsylvania, 66 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	500022028100000	US 22/322; SR 0022	3 MI.N. OF AMITY HALL
2	220081065200000	I-81; SR 0081	HARRISBURG (WADE BR)
3	220039002006520	PA 39; SR 0039	0.5 MI S OF ROCKVILLE
4	220039002012780	PA 39; SR 0039	INTER OF US22 & PA39
5	220300001009640	PA 283; SR 0300	1 MI N HIGHSPIRE
6	220300002000000	PA 283; SR 0300	1 MI. N. HIGHSPIRE
7	530061034008980	SR 61 (LR 140)	NEAR INTERSECTION US209
8	530061034000430	PA 61(LR 140)	NEAR POTTSVILLE CITY LINE
9	60422010002590	SR 422(LR 149)	WOMELSDORF BOROUGH
10	530061017000310	SR 61 (LR 141)	AT S.LIBERTY STREET
11	530081134110750	I-81 SB (LR 1005)	0.4 MI.N.OF EXIT 134(38)
12	530081136500000	I-81 SB (LR1005)	2.7 MI.N.OF EXIT 134(38)
13	530081136400000	I-81 NB (LR1005)	2.7 MI.N.OF EXIT 134(38)
14	530081137516840	I-81SB(LR 1005)	EXIT 138(39) MCADOO EXIT
15	60061035017810	SR 61(LR 160)	HAMBURG BOROUGH
16	530309026000000	PA 309(LR 226)	CENTER ST,TAMAQUA
17	530309008024730	PA 309(LR 226)	LEIBEYVILLE,WEST PENN PK.
18	530309006011150	PA 309 (LR 226)	SNYDERS
19	60222051000000	US 222 (LR 157)	S.END OF KUTZTOWN BYPASS
20	60078041014700	SR 78(LR 285 SP)	GRIMVILLE