




## Structurally Deficient Bridges on the National Highway System Texas - Congressional District 02



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 184 structurally deficient NHS bridges in Texas, 15 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

<b>Bridge Label</b>	<b>Structure ID</b>	<b>Bridge Description</b>	<b>Location Description</b>
1	201460033805087	SH 105	0.2 MI E OF FM 1725
2	121020002801007	US90 BUS	2.40 MI E OF SHELDON RD
3	201460C00670001	SANDUNE RD	0.8 MI NE OF SH 146
4	201240020011103	US 69 SB	0.8 MI S OF SH 105
5	201240002813082	IH 10 ML	1.2 MI E OF US 69
6	201810002809065	IH 10	0.00 MI E JEFFERSON C/L
7	201240050805034	SH 82	0.7 MI SE OF SH 73
8	201240020016142	US 69,96,287	1.5 MI N OF SH 73
9	201240050804166	25TH STREET	0.6 MI W OF SH 87
10	201240050804165	SH 73	0.3 MI W OF SH 87