




Structurally Deficient Bridges on the National Highway System Texas - Congressional District 06



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2005, all data is from the 2007 NBI. Of the 154 structurally deficient NHS bridges in Texas, 15 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	22200106802054	FM-157 NBL	2.0 MI W OF SH-360
2	22200106802053	RAMP G	0.2 MI N OF IH-30
3	22200106802145	SH360 WFR	1.2 MI N OF US-80
4	181750B01045001	N. 15 STREET	0.4 MI N OF SH 31
5	181750009301060	IH 45 WFR	0.60 MI N OF SH 14
6	181750009301061	IH45 EFR	0.60 MI N OF SH 14
7	170820067502156	IH 45 WFR	5.9 MI S OF FM 489