




Structurally Deficient Bridges on the National Highway System Texas - Congressional District 13



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 184 structurally deficient NHS bridges in Texas, 15 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	41710006604004	US287	1.730 MI NO OF FM 119
2	41910016808067	US 60 NB	CANYON INTCHG
3	41880004105053	US 87 SB	11.5 MI S MOORE CO LINE
4	41880016810060	IH 27 NB	IH 27 @ 26TH ST
5	41880027501016	IH 40 EB	I 40 MP 71.1
6	32440004305104	US 287 NB	0.3 MI N OF US 70
7	21200017101002	SH 199	2.6 MI W OF FM-1156
8	31690001302002	US 81	1.4 MI S OF RED RIVER