




Structurally Deficient Bridges on the National Highway System Texas - Congressional District 26



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 184 structurally deficient NHS bridges in Texas, 15 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	22200000813081	IH 20 EB FTG RD	0.9 MILE EAST OF I-35W
2	022200ZB2880002	BERRY STREET	0.1 MI E OF RIVERSIDE DR
3	22200017206059	US 287 NB	0.3 MI N OF MITCHELL BLVD
4	22200000813093	I 20 EB	0.2 MI W OF BU 287
5	22200017206068	US 287 SB	0.196 MI N OF IH-820
6	22200000813165	US 287 WB RAMP	0.2 MI W OF IH 820 NB
7	22200000813105	IH820 SBL	1.1 MI S OF US-80
8	22200000813103	IH820 SBL	0.3 MI S OF US-80
9	22200000813136	SH 183 WB	1.0 MI S OF PIPELINE
10	22200000813313	SH 183 EB	1.0 MI S OF PIPELINE RD
11	180610019503047	IH 35E SBML	1.60 MI NW OF US 377